



Freedom of Information Request

24 January 2023

Question

I would like to know:

Please forward all information you hold with specific focus on service and repair history for a 2009 Renault Master Scottish Ambulance: Registration : SF59 BVY

Answer

Please see table below showing vehicle service history for vehicle SF59 BVY. The vehicle maintenance history of any Scottish Ambulance Service vehicle may not accurately reflect that vehicle at time of sale or disposal. To ensure best use of public funding, vehicles are assessed prior to sale or disposal and it is normal for vehicle markings, warning systems, operating components and reusable parts to be removed from the vehicle for further use or disposal. Vehicles and equipment sold through auction are sold subject to the terms and conditions of that auction sale. No guarantee of vehicle, components or equipment age, condition or warranty is offered or implied.

The Service will not release documents/information that could compromise the safety or security of any vehicles or staff. Where information may be commercially sensitive, copyright or of intellectual value to the vehicle manufacturer/converter, requests should be made to that manufacturer/converter.

Reg no	Completion date	Serv desc	Odo
SF59BVY	23/02/2011	SERVICE	18000
SF59BVY	23/11/2011	SAFETY CHECK	32178
SF59BVY	27/02/2012	SERVICE	35355
SF59BVY	27/02/2012	SAFETY CHECK	35355
SF59BVY	28/05/2012	SAFETY CHECK	38232
SF59BVY	28/08/2012	SAFETY CHECK	43799
SF59BVY	22/11/2012	MOT	43623
SF59BVY	22/11/2012	SAFETY CHECK	43623
SF59BVY	25/03/2013	SAFETY CHECK	48571
SF59BVY	15/11/2013	SERVICE	56051
SF59BVY	25/03/2013	SAFETY CHECK	48571
SF59BVY	26/06/2013	SAFETY CHECK	52111
SF59BVY	15/11/2013	SAFETY CHECK	56051
SF59BVY	24/11/2013	SAFETY CHECK	55782
SF59BVY	24/11/2013	MOT	55782
SF59BVY	15/11/2013	MOT	56052
SF59BVY	25/02/2014	SAFETY CHECK	59617
SF59BVY	29/10/2014	SAFETY CHECK	72121
SF59BVY	29/10/2014	SERVICE	73112
SF59BVY	27/11/2014	MOT	74694
SF59BVY	27/11/2014	SAFETY CHECK	74694
SF59BVY	02/04/2015	SAFETY CHECK	80602
SF59BVY	02/10/2015	SAFETY CHECK	89955
SF59BVY	02/10/2015	SAFETY CHECK	89955

Working Together for Better Patient Care

SF59BVY	02/10/2015	SERVICE	89955
SF59BVY	12/11/2015	MOT	90971
SF59BVY	12/11/2015	SAFETY CHECK	0
SF59BVY	09/03/2016	SAFETY CHECK	98700
SF59BVY	27/06/2016	SAFETY CHECK	105842
SF59BVY	27/07/2016	SERVICE	0
SF59BVY	16/09/2016	SERVICE	109334
SF59BVY	16/09/2016	SAFETY CHECK	109712
SF59BVY	24/11/2017	MOT	114875
SF59BVY	24/11/2016	SAFETY CHECK	114455
SF59BVY	23/03/2017	SAFETY CHECK	119684
SF59BVY	10/07/2017	SAFETY CHECK	126578
SF59BVY	10/07/2017	SERVICE	127393
SF59BVY	13/10/2017	SAFETY CHECK	134531
SF59BVY	27/11/2017	SAFETY CHECK	137113
SF59BVY	27/11/2017	SAFETY CHECK	137113
SF59BVY	26/01/2018	SERVICE	141790
SF59BVY	19/02/2018	SAFETY CHECK	141185
SF59BVY	22/02/2018	SERVICE	141790
SF59BVY	23/02/2018	SERVICE	141790
SF59BVY	05/04/2018	SAFETY CHECK	147497
SF59BVY	27/07/2018	SAFETY CHECK	148390
SF59BVY	19/10/2018	SAFETY CHECK	153583
SF59BVY	25/10/2018	MOT	153863
SF59BVY	09/01/2019	SAFETY CHECK	156229
SF59BVY	09/01/2019	SERVICE	157489
SF59BVY	30/04/2019	SAFETY CHECK	159034
SF59BVY	30/04/2019	SERVICE	162332

Working Together for Better Patient Care

SF59BVY	29/07/2019	SAFETY CHECK	165782
SF59BVY	21/10/2019	SAFETY CHECK	170952
SF59BVY	21/10/2019	MOT	170952
SF59BVY	18/11/2019	MOT	172155
SF59BVY	27/01/2020	SAFETY CHECK	175946
SF59BVY	04/04/2020	SAFETY CHECK	178131
SF59BVY	04/04/2020	SERVICE	178131
SF59BVY	02/07/2020	SAFETY CHECK	178993
SF59BVY	15/10/2020	SAFETY CHECK	184164
SF59BVY	22/11/2020	MOT	186725
SF59BVY	26/01/2021	SAFETY CHECK	191846

Working Together for Better Patient Care